## Oil Field Environmental Incident Summary

Responsible Party: OXY USA INC.
Well Operator: OXY USA INC.
Well Name: KUNTZ 1-23-14H-142-98

Field Name: SADDLE BUTTE Well File #: 23088

Date Incident:10/18/2014Time Incident:08:30Facility ID Number:County:BILLINGSTwp:142Rng:98Sec:23Qtr:

**Location Description:** 

Submitted By: Rebecca Zent Received By:

Contact Person: Rebecca Zent

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

**Brine** 

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 12/15/2015 Clean Up Concluded: 10/19/2015

Risk Evaluation:

None

Areal Extent:

## Potential Environmental Impacts:

None

## Action Taken or Planned:

Fire was extinguished by local fire department

Wastes Disposal Location:

Agencies Involved: Local Fire Department

**Updates** 

Date: 10/24/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Fire on location. No liquid release according to the report. NDIC retains oversight.